


CORNER RECORD

Document Number 3719 (3)

City of _____

County of MERCED, California

Brief Legal Description MONUMENT AT THE INTERSECTION OF SHANKS ROAD AND LETTEAU AVENUE.



SEC.8 T6S, R11E

CORNER TYPE

Government Corner Control
 Meander Property
 Rancho Other

Date of Survey 01-07-2013

COORDINATES (Optional)

N _____
 E _____
 Zone _____ NAD27 NAD83
 NAD83 Epoch _____
 Elev. _____
 Vert. Datum: NVGD29 NVGD88
 Meas. Units: Metric Imperial

Corner- Left as found Found and tagged Established Reestablished Rebuilt

Identification and type of corner found: Evidence used to identify or procedure used to establish or reestablish the corner:
SET BRASS DISK STAMPED L.S. 6953 IN MONUMENT WELL, AT THE INTERSECTION OF SHANKS ROAD AND
LETTEAU AVENUE. MONUMENT WAS DESTROYED DURING CONSTRUCTION. FOUND WITNESS CORNERS AS SHOWN
ON CORNER RECORD DOCUMENT NUMBER 3719, MERCED COUNTY RECORDS.

A description of the physical condition of the monument as found and as set or reset: _____
SET BRASS DISK STAMPED L.S. 6953 IN MONUMENT WELL FROM TIES AS SHOWN ON PAGE 2.

SURVEYOR'S STATEMENT

This Corner Record was prepared by me or under my direction in conformance with
 the Land Surveyors' Act on JANUARY 14, 2013,

Signed [Signature] P.L.S. or R.C.E. Number 6953



COUNTY SURVEYOR'S STATEMENT

This Corner Record was received February 5, 2013 and examined
 and filed February 6, 2013

Signed [Signature] P.L.S. or ~~R.C.E.~~ No: 4895

Title Acting County Surveyor

County Surveyor's Comment _____



LEGEND:

- ⊗ SET MONUMENT AS NOTED
- FOUND MONUMENT AS NOTED.
- M.C.R. DENOTES MERCED COUNTY RECORDS
- C.R. DENOTES CORNER RECORD
- (M) MEASURED DISTANCE. ALL DISTANCES ARE MEASURED UNLESS NOTED OTHERWISE.

REFERENCE:

(R1) C.R.-3719, M.C.R.

